



Product and debris pooling in corner of
DPS 19 forebay



08/05/2018 10:03:38
New Orleans

No product on discharge side of DPS 19



08/05/2018 09:49:16
New Orleans



OMI crew cleaning product out of forebay

08/05/2018 12:43:50
New Orleans




08/05/2018 14:13:41
New Orleans




OMI crew cleaning product out of forebay

08/05/2018 14:12:47
New Orleans



Turtles taken from affected area and cleaned

08/05/2018 15:43:46
New Orleans



Duckling taken from affected area and cleaned

08/05/2018 14:07:07
New Orleans



LDWF collecting 3 ducklings and 2 turtles

08/05/2018 18:28:26
New Orleans

Product cleaned out of forebay



08/05/2018 18:27:43
New Orleans



08/05/2018 18:25:52
New Orleans

PHOTOS - MONDAY AUGUST 6TH 2018


Hydrants inside Naval Base flushing the drainage line



Green dye in drainage manhole



Green tint in Florida Canal at Alvar box culvert outfall indicating dye traveled from the source site along with the hydrant flush water.





DPS 19 forebay at the
end of Monday